



Rev.	Modify	Date	Signed	Approved



ALL RIGHTS ARE RESERVED.

A₄



Rev.	Modify	Date	Firma	Approved




PACKAGING:


Connectors must be already assembled with the fixing screw, but ****without**** the gasket of the connector. You have to pack the connectors in plastic bags, without any label and every single plastic bag must contain 50 connectors.

Moreover you have to pack the gaskets (that you have ****not assembled**** on the connectors) in "separate" plastic bags (****not**** together with the connectors) and every single plastic bag (without any label, too) must contain 50 gaskets.

PLASTIC BAG CONTAINING 50 CONNECTORS
ALREADY ASSEMBLED WITH CENTRAL FIXING SCREW.



PLASTIC BAG CONTAINING 50 SQUARE GASKETS



CONNECTORS WITHOUT SQUARE GASKETS

CUSTOMER APPROVAL

SIGNATURE	DATE

PLEASE SIGN
AND RETURN

Designer	CIMMINO L.	Date	2019-04-08	Tolerance	±0,3	Units:	mm	Series	INDUSTRIAL CONNECTOR	Drawing n.	2-2
Approved	SUGLIANI R.	Date	2019-04-08	Scale	1:1	Size:	A4	Customer code:			



DESCRIPTION

INDUSTRIAL CONNECTOR, 16x16mm, FIELD ATTACHABLE, N°4 POLES, WITHOUT ELECTRONIC, 50V AC/DC, BLACK, PG7, WITH STAINLESS STEEL SCREW L=23mm. CONNECTOR WITH H.T.P. LOGO.

H.T.P. PART NUMBER

P3NZ4000

A4

